

Model	Solution
TM-P60II	Workaround
TM-P80	Workaround
TM-P20	Workaround
TM-m10	Fixed firmware
TM-m30	Fixed firmware
TM-T20II(**7)	Workaround
TM-T88VI	Fixed firmware
TM-T88VI-iHUB	Fixed firmware
TM-H6000V	Fixed firmware
TM-T100E	Fixed firmware
TM-T100M	Fixed firmware
TM-T100N	Fixed firmware
TM-T100S	Fixed firmware
TM-T100W	Fixed firmware
TM-T20IIIL	Fixed firmware
TM-T20X	Fixed firmware
TM-T81III	Fixed firmware
TM-T82IIIL	Fixed firmware
TM-T82X	Fixed firmware
TM-T83III	Fixed firmware
TS-100	Workaround
TM-T20III	Fixed firmware
TM-T82III	Fixed firmware
TM-m30II	Fixed firmware
TM-m30II-H	Fixed firmware
TM-m50	Fixed firmware
TM-m30II-NT	Fixed firmware
TM-m30II-S	Fixed firmware
TM-m30II-SL	Fixed firmware
TM-L100	Fixed firmware
UB-R04	Workaround
UB-E04	Fixed firmware
UB-R05	Fixed firmware